

Location: Annacotty, Co. Limerick		Unique ID: 252771 (from PFRA database)	
Initial OPW Designation	APSR <input type="checkbox"/>	AFRR <input checked="" type="checkbox"/>	IRR <input type="checkbox"/>
Co-ordinates	Easting: 165211	Northing: 158095	
River / Catchment / Sub-catchment	Tributary to the Mulkear / Shannon		
Type of Flooding / Flood Risk (identify all that apply)	Fluvial non-tidal <input checked="" type="checkbox"/> Fluvial tidal <input type="checkbox"/> Coastal <input type="checkbox"/>		

Stage 1: Desktop Review	
1.1 Flood History (include review of Floodmaps.ie)	<p>River Flow Path The tributary to the Mulkear at the Annacotty AFRR flows north and west towards it's confluence with the Mulkear.</p> <p>Flood Event Records There are records of eleven flood events for Annacotty on floodmaps.ie. The town of Annacotty is a suburb of Limerick City and is included in the Limerick APSR.</p> <p>The Annacotty area for flood risk review, based on the coordinates supplied by OPW, is east of Annacotty town – this is the area which has been considered under this flood risk review.</p>
1.2 Relevant information on flooding issues from OPW and LA staff	<p>PFRA database comments (<i>in italics</i>):</p> <p><i>OPW comments</i> <i>Not designated APSR as failed to reach predictive analysis threshold No properties - No Predictive - No FHM Historic</i></p> <p><i>LA comments</i> <i>Annacotty-Mulkear Road.(am) access to houses flooded</i></p> <p>Meeting / discussion summary comments:</p> <p>OPW comments</p> <ul style="list-style-type: none"> OPW comments were focused on the village of Annacotty and they have no comments on the flood risk within AFRR Annacotty <p>LA comments</p> <ul style="list-style-type: none"> Limerick CC comments were focused on the village of Annacotty and they have no comments on the flood risk within AFRR Annacotty

1.4 PFRA Data			
1.4.1 PFRA hazard mapping	PFRA mapping available in GIS layer:		Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	PFRA mapping included on FRR map:		Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
1.4.2 Summary of Principal Receptors	Type	FRI score (if available)	
	Receptors not considered as part of the PFRA process. FRI score not calculated in PFRA.		
1.7 Stage 1 Evaluation	Aspect	Clearly APSR	Uncertain
	Flood History (1.1)		X
	OPW / LA Information (1.2)		X
	PFRA Evaluation (1.4)		X
	Overall Desktop Evaluation (if any above aspect is uncertain then overall designation is uncertain)		X
1.8 Proposed level of assessment for Stage 2 site visits	Level A Site Visit		X
	Level B Site Visit		

Stage 2: Site Inspection		Level A Assessment		
Date and Time of Inspection		Date: 09/06/11		
		Time: 13:00		
Names of inspection team (including OPW/LA staff if present)		Mathieu Valois		
		James Murray		
2.1 Ground-truthing of Hazard Mapping	Fluvial non-tidal <input checked="" type="checkbox"/> Fluvial tidal <input type="checkbox"/> Coastal <input type="checkbox"/> Not available <input type="checkbox"/> PFRA hazard mapping seems reasonably accurate.			
2.2 Spot check ground-truthing of selected receptor vulnerability (also note any key receptors noted during visit that are not identified by PFRA)	Receptor Type	Location description (if not obvious)	Exists?	Overall Vulnerability / Risk (L / M / H)
	There is a public house / restaurant	Situated on the left bank of the tributary	Yes	Low
2.3 Local knowledge - on-site comments (OPW, LA and any info volunteered by local residents during visit)	No on-site comments			
2.4 Comments on hydraulic constrictions (bridges, etc.) and conveyance routes	There is a 450 diameter culvert in the corner of the public house car park. The culvert may provide a hydraulic constraint. However, this is unlikely to result in flooding as there is sufficient channel and floodplain capacity upstream of the culvert.			

2.5 SVRS Assessment Matrix

Weightings:

A - x1 - reasonable expectation of flooding

B - x2 - high expectation of flooding

C - x5 - risk to life

Approx. Number	1 to 4				5 to 20				>20			
Weighting		A	B	C		A	B	C		A	B	C
Property (domestic)	10				100				200			
Property (small retail or business)	20				200				400			
Property (large retail or business)	50				500				1000			
Road or Rail Infrastructure	30				300				600			
Critical Infrastructure (local) [hospital, school, police/fire/ambulance station, substation, WTW/WWTW, gov bldg, other (specify)]	50				500				1000			
Critical Infrastructure (national importance)	250				1000				2000			
Cultural Heritage Site	20				200				400			
Environmental Designated Site	20				200				400			
Hazardous Substances Site	50				500				1000			
Total SVRS								0				

2.6 Defence Assets

Formal and Informal Flood Defence Assets
(include effective and ineffective assets to inform asset survey and potential mitigation measures)

Open Channel Watercourses

Man-made river channel ☐ Flood relief channel ☐ Canal ☐
Mill leat ☐ Drainage channels / back drains ☐

Bridges and Culvert crossings

Single Arch bridge ☐ Multi-Arch bridge ☐
Single Span bridge ☐ Multi-Span bridge ☐
Box culvert(s) ☐ Pipe culvert(s) ☒ Arch Culvert(s) ☐

Culverted Watercourses (culvert length is greater than just a crossing)

Box culvert(s) ☐ Pipe culvert(s) ☐ Arch Culvert(s) ☐ Irregular Culvert(s) ☐

Walls and Embankments

Embankment(s) ☐ Raised wall(s) ☐ Retaining wall(s) ☐

Control Structures – weirs, gates, dams

Fixed crest weir ☐ Adjustable weir ☐ Dam / Barrage ☐
Sluice gates ☐ Lock gates ☐ Radial gates ☐

Storage

On-line storage (natural) ☐ On-line storage (artificial) ☐ Off-line storage ☐

Outfalls

Flapped outfall(s) into watercourse ☐ Unflapped outfall(s) into watercourse ☐
i.e. from smaller watercourses, drains etc. into river / estuary / sea
Tidal flap(s) ☐ Tidal sluice(s) ☐
i.e. from main watercourse into estuary / sea

	Other Pumping Station <input type="checkbox"/> Erosion Protection <input type="checkbox"/> Sand Dunes <input type="checkbox"/> Additional notes (if required):
2.8 Initial Potential Mitigation Measures	
Non-structural measures	Planning and Development control <input type="checkbox"/> Sustainable Urban Drainage Systems <input checked="" type="checkbox"/> Flood forecasting / warning <input type="checkbox"/> Change in Operating Procedures for water level control: <input type="checkbox"/> Public awareness campaign <input checked="" type="checkbox"/> Individual property protection <input checked="" type="checkbox"/> Land use management <input type="checkbox"/>
Structural measures	Strategic development management for floodplain development: <input type="checkbox"/> <i>(integration of measures into strategic development proposals)</i> Storage: On-line <input type="checkbox"/> Off-line <input type="checkbox"/> Flow diversion: Flood relief channel <input type="checkbox"/> Flood relief culvert <input type="checkbox"/> Increase conveyance: Bridge works <input type="checkbox"/> Channel works <input type="checkbox"/> Floodplain <input type="checkbox"/> Flood defences: Walls <input checked="" type="checkbox"/> Embankments <input type="checkbox"/> Localised works: Defence raising <input type="checkbox"/> In-fill gaps <input type="checkbox"/> Trash screen <input type="checkbox"/> Maintenance works: Culvert / channel clearance <input checked="" type="checkbox"/> Asset maintenance <input checked="" type="checkbox"/> Relocation of properties: <input type="checkbox"/> Improve existing defences: <input type="checkbox"/> (describe) Other (describe):

Outcomes				
PFRA Designation	APSR <input type="checkbox"/> not an APSR <input checked="" type="checkbox"/> IRR <input type="checkbox"/>		FRI Score: Not scored	
Site Ground-truthing of PFRA Assessment (hazard mapping and receptors)	High Confidence (good)	Uncertain	Low Confidence (poor)	Not available
	X			
Site Visit Review Score	0			
Recommended Designation	APSR <input type="checkbox"/> not an APSR <input checked="" type="checkbox"/> IRR <input type="checkbox"/>			
Summary Comments (if required)	Annacotty village is part of the Limerick APSR. The area for which this flood risk review was carried out, as defined in the project brief is not at significant risk of flooding to warrant designation as an APSR.			



Photo1: Watercourse upstream of road culvert.



Photo 2: Pub / restaurant off left bank of watercourse.

